

# The Value of Simple Checks

*Conference on Quality in  
the Space and Defense  
Industries*

*March 19, 20, 2012*

*Joe Nieberding*



*Aerospace  
Engineering Associates LLC*

The logo for Aerospace Engineering Associates LLC features a stylized white arrow pointing upwards and to the right, with the word "Aerospace" in a large, white, serif font and "Engineering Associates LLC" in a smaller, white, sans-serif font below it.



# Simple Checks Can Be Very Effective

- Frequently, engineers believe that “checking” anything complex always requires potentially costly or time-consuming testing
- Sometimes, just a simple check would be adequate to uncover a problem
- But such checking requires a knowledge of how a system really works, as well as understanding of the “real world” physics behind the complicated mathematics






# STS-51 TOS/ACTS Separation Band Anomaly

- **Underlying Issue:** Design error made it to flight
- **Problem:** STS-51 Orbiter damaged by debris from ruptured separation joint upon ACTS/TOS deployment (9/12/93)
- **Why:** Improper design of Super Zip firing circuits. **No simple electrical interface drawing check performed.**
- **Impact:** **Damage to Orbiter**
  - **Nearly impacted flight/crew critical equipment:**
    - One piece penetrated Orbiter aft bulkhead blanket and caused a 1/8 x 1/2 inch hole in bulkhead
  - **Other debris caused:**
    - At least 9 tears in cargo bay insulation blankets
    - 3 gouges in wire tray covers
    - Possibly a gouge in a TPS tile




# STS-51 TOS/ACTS Separation Band Anomaly (cont'd)




# STS-51 TOS/ACTS Separation Band Anomaly (cont'd)

**Should Be\***



**Was\***



NASA Glenn Research Center  
Pyro Testing  
Rigorous Configuration Control  
**Safety First!**


# STS-51 TOS/ACTS Separation Band Anomaly (concluded)

## **LESSONS:**

- **Never implement an electrical interface based on nomenclature**
  - **Verify compliance with design intent by examining the entire circuit**
  - **Produce end-to-end (cross interface boundaries) schematics for all electrical systems**
- **Test procedures should be based on functional requirements whenever possible**
  - **Not just to verify “built to print”**
- **Be extremely vigilant when implementing any interface – historically, this is a “hot spot” for mistakes!**


# AC-34: Mariner Venus/Mercury - Mariner 10

- Launched successfully: November 3, 1973
- Underlying Issue: Error in implementing spacecraft interface to launch vehicle
- Problem: Spacecraft X-axis polarity reversed in launch vehicle ascent trajectory simulation
  - Caught by simple check 3 years before launch
- Potential impact if undetected: **Damaged spacecraft instruments**
- Actual impact: **None – Mission successful**
  - **Ended March, 1975, after one Venus and three Mercury passes**
  - **First dual planet mission - 12,000 images**
    - **First clear pictures of Venusian clouds**
    - **First use of gravity assist**
    - **First mission to Mercury**



Venus in real color

Venus in ultraviolet



Mercury in real color





Source: Subject matter expert: J. Nieberding, lead launch vehicle mission analyst



# AC-34: Mariner Venus/Mercury - Mariner 10 (cont'd)

## Simple spacecraft model




Complex

Simple



# AC-34: Mariner Venus/Mercury - Mariner 10 (cont'd)

- **Spacecraft instruments must not point toward sun**
  - Centaur coast phase roll attitude so programmed
- **Trajectory listing reviewed**
  - Listing attitude was manually compared with expected attitude as determined through observation of model and globe relative geometry
  - Comparison revealed problem
- **Trajectory simulation code had the spacecraft X-axis polarity reversed!**
  - **If undetected, serious spacecraft damage likely**




## **LESSONS:**

- **Be extremely vigilant when implementing any interface (between systems, NASA centers, contractors, etc.) – historically, this is a “hot spot” for mistakes!**
- **Simple checks can be very effective**
- **Must understand the real world physics, not just the mathematics**

## Conclusion

- Look for ways to perform simple checks
- If “it” doesn’t pass a simple test, “it” may be wrong
- Remember, as Mark Twain once said:

*“It ain’t what you don’t know  
that gets you into trouble. It’s  
what you know for sure that just  
ain’t so.”*





Joe Nieberding, President  
Email: joenieber@wowway.com  
Cell: 440-503-4758



P. O. Box 40448  
Bay Village OH 44140  
[www.aea-llc.com](http://www.aea-llc.com)



Larry Ross, CEO  
Email: ljross1@att.net  
Cell: 440-227-7240

## **MISSION**

**AEA's mission is to leverage the vital lessons learned by NASA's spacefaring pioneers to strengthen the skills of today's aerospace explorers.**